



Erede Rossi Silvio
azienda agricola trotilcoltura










Controllo della profondità della falda idrica



Impianto: Via Madonna dei calcinai, 2 Sefro (MC)

REGISTRO PROFONDITA' FALDA

N.	DATA	N. POZZO	PROFONDITA' POZZO [m]	PROFONDITA' FALDA DAL PIANO CAMPAGNA [m]	PROFONDITA' FALDA RILEVATA [m]	FIRMA
1	16/04/2014	1	4,00	3,00	2,80	
2	21/10/2014	2	4,00	3,00	3,30	
3	22/04/2015	3	4,00	3,00	2,90	
4	22/10/2015	4	4,00	3,00	3,20	
5	21/04/2016	5	4,00	3,00	2,80	
6	24/10/2016	7	5,00	3,00	3,20	
7	18/04/2017	8	5,00	3,00	2,90	
8						
9						
10						
11						
12						
13						
14						
15						
16						
17						
18						
19						
20						
21						
22						
23						
24						
25						
26						
27						
28						
29						
30						